

Hole No. CB-DAC-24

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Jacksonville District		SHEET 1 OF 1 SHEETS	
1. PROJECT Dade County Beach Restoration				10. SIZE AND TYPE OF BIT Vibrocure 3-1/2"			
2. LOCATION (Coordinates or Station) X=798 963 Y=531 778				11. DAYUM FOR ELEVATION SHOWN (TBM or MSL) MLW			
3. DRILLING AGENCY Alpine Geophysical (Contract)				12. MANUFACTURER'S DESIGNATION OF DRILL Vibrocure			
4. HOLE NO. (As shown on drawing title and file number) CB-DAC-24				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED	
5. NAME OF DRILLER J. Katsolis				14. TOTAL NUMBER CORE BOXES 1		15. ELEVATION GROUND WATER Tidal	
6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED _____ DEG. FROM VERT.				16. DATE HOLE 5-27-74		STARTED COMPLETED 5-27-74	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE -48.7			
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING 74 %			
9. TOTAL DEPTH OF HOLE 10.9'				19. NAME OF INSPECTOR GEOLOGIST: T. M. THORNTON			

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOV- ERY e	BOX-OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g
-48.7	0.0					
			SAND, calcareous, medium to coarse, numerous shell fragments, scattered shells and coral fragments to cobble size, tan gray (SP)		1	3-1/2" Vibrocure
-58.2	9.5		Below 9.5' numerous sand-stone lenses		2	
-59.6	10.9					