

# GAHAGAN & BRYANT ASSOCIATES

P.O. BOX 18505 TEL. 813-879 5871  
TAMPA, FLORIDA 33679

## LOG OF BORING



SUBJECT Jupiter Island  
 BORING LOCATION 22+00 Cut M-17 Range +400  
 GROUNDWATER DEPTH \_\_\_\_\_ DATE \_\_\_\_\_  
 DRILL ROD SIZE AW CASING SIZE \_\_\_\_\_ BW \_\_\_\_\_  
 BORING BEGUN \_\_\_\_\_ BORING COMPLETED \_\_\_\_\_  
 TIME AT START 1245 TIME AT FINISH 1430  
 TIDE AT START +1.1 TIDE AT FINISH +1.4  
 GEOLOGIST \_\_\_\_\_

BORING NO. 37  
 CLIENT Jupiter Island  
 DATE 7-17-76 SHEET 1 OF 2  
 DRILL RIG Bore Hog  
 DRILLER Rowland  
 LENGTH OF CASING SET 23'  
 GROUND ELEVATION \_\_\_\_\_ DATUM MLW

ELEVATION	DEPTH IN FEET	SOIL GRAPH	MATERIAL DESCRIPTION	REMARKS	SAMPLE NUMBER	ON SAMPLE	ON CASING	DEPTH IN FEET
	1							1
	2							2
	3							3
	4							4
	5							5
	6							6
	7							7
	8							8
7.7	9							9
	10							10
9.9	11		Very Silty Fine to Medium Sand	No Recovery 9' to 11'	37-1	WOH	2	11
	12						1	12
	13		Fine to Medium Sand				4	13
12.8	14						16	14
	15						16	15
13.8	16		Shell Fragments w/soft Clay				15	16
	17						21	17
	18		Fine to Medium White Sand				14	18
17.6	19				37-2		10	19
	20						10	20
							14	
							25	
18.6							45	
							60	
			Shell & Clay Frag.					

BORING NO. 37

DATE 7-17-76 SHEET 2 OF 2

ELEVATION	DEPTH IN FEET	SOIL GRAPH	MATERIAL DESCRIPTION	REMARKS	SAMPLE NUMBER	BLOWS / FOOT		DEPTH IN FEET
						ON SAMPLE	ON BLANK	
20.6	21		Stiff Gray Clay		37-3	5	58	21
	22					7	70	22
23.6	23		Fine to Medium Tan Sand		37-4		70	23
	24					6		24
	25					7		25
	26							26
	27							27
	28							28
	29							29
	30							30
	31							31
	32							32
	33							33
	34							34
	35							35
	36							36
	37							37
	38							38
	39							39
	40							40
	41							41
	42							42
	43							43
	44							44
	45							45
	46							46