



SIEVE ANALYSIS TOPB_VC_07.GPJ FL DEP ROSS.GDT 5/10/07



| Gravel | | Sand | | | Silt and Clay |
|--------|------|--------|--------|------|---------------|
| Coarse | Fine | Coarse | Medium | Fine | |

| Sample | Symbol | Elev. (ft) | USCS | % Fines | % Organics | % Carbonates | Median | Mean | Skew | Kurt | Sort | Sample Information | |
|---|--------|------------|------|----------------------------|------------|--|--------|------|-------|-------|------|--------------------|--------------------------------|
| TPVC-07-11 #6 | —●— | -37.1 | SP | #200 - 1.98 #230 - 1.95 | | | 2.54 | 2.4 | -2.04 | 10.76 | 0.64 | Project Name: | 2007 Sand Search Investigation |
| Comments: | | | | | | | | | | | | Analysis Date: | 01-29-07 |
| Depths and elevations based on measured values | | | | | | | | | | | | Analyzed By: | mc |
|  | | | | | | Coastal Planning & Engineering 2481 NW Boca Raton Blvd, Boca Raton FL 33431 ph (561) 391-8102 fax (561) 391-9116 | | | | | | Easting (X, ft): | 972,457 |
| | | | | | | | | | | | | Northing (Y, ft): | 822,632 |
| | | | | | | | | | | | | Horizontal System: | NAD 1983 |
| | | | | | | | | | | | | Vertical System: | NAVD 88 |