


JET PROBE LOG		DIVISION		INSTALLATION		SHEET 1 OF 1 SHEETS	
1. PROJECT Mexico Beach Sand Search Bay County, Florida							
2. JET PROBE DESIGNATION MBJP-18-06				LOCATION COORDINATES (ft) X = 1,665,049 Y = 336,719			
3. DRILLING AGENCY APTIM				CONTRACTOR FILE NO.			
4. NAME OF DRILLER Franky Stankiewicz				9. SIZE OF PROBE 1.5 In.			
5. DIRECTION OF JET PROBE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED				10. COORDINATE SYSTEM/DATUM Florida State Plane North		HORIZONTAL NAD 1983	
6. THICKNESS OF OVERBURDEN				11. MANUFACTURER'S DESIGNATION OF PROBE APTIM Jet Probe			
7. DEPTH DRILLED INTO ROCK				12. TOTAL SAMPLES		DISTURBED	
8. TOTAL DEPTH OF JET PROBE 20.0 Ft.				3		UNDISTURBED (UD)	
13. TOTAL NUMBER BOXES				14. ELEVATION GROUND WATER			
15. DATE OF JET PROBE				STARTED		COMPLETED	
12-17-18 13:25				12-17-18 13:25		12-17-18 13:40	
16. ELEVATION TOP OF JET PROBE -17.2 Ft.				17. TOTAL RECOVERY FOR JET PROBE 20 Ft.			
18. SIGNATURE AND TITLE OF INSPECTOR Franky Stankiewicz							
ELEV. (ft)	DEPTH (ft)	LEGEND	CLASSIFICATION OF MATERIALS Depths and elevations based on measured values	% REC.	BOX OR SAMPLE	REMARKS	
-17.2	0.0						
-19.2	2.0		SAND, fine grained, light gray (2.5Y-7/1), (SP).		1	Sample #1, Depth = 0.0' Mean (mm): 0.22, Phi Sorting: 0.54 Fines (230): 1.20% (SP)	
-25.2	8.0		Shelly SAND.				
-29.2	12.0		SAND, fine grained, light gray (2.5Y-7/1), (SW).		2	Sample #2, Depth = 10.0' Mean (mm): 0.42, Phi Sorting: 2.13 Fines (230): 1.15% (SW)	
-30.2	13.0		Shelly SAND.				
-33.2	16.0		SAND.				
-34.2	17.0		Shelly SAND.				
-37.2	20.0		SAND, fine grained, light gray (5Y-7/1), (SW).		3	Sample #3, Depth = 20.0' Mean (mm): 0.26, Phi Sorting: 1.00 Fines (230): 1.13% (SW)	
			End of Jet Probe				