



SIEVE ANALYSIS: SINGER_IS.GPJ FL DEP ROSS.GDT 9/7/04




SIEVE ANALYSIS: SINGER_IS.GPJ FL DEP ROSS.GDT 9/7/04



Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	

Sample	Symbol	Elev.	Comments	USCS	% Fines	Median	Mean	Skew	Kurt	Sort	Sample Information	
SI04-17 #4.0	—●—	-56.5		SP	#200 - 1.07 #230 - 1.60	1.9	1.77	-0.62	3.23	0.85	Project Name:	Palm Beach County Vibracore 2004
											Analysis Date:	07-01-04
											Analyzed By:	SEA Inc.
Scientific Environmental Applications, Inc. 5575 Willoughby Drive Melbourne, FL 32934 (321) 254-2708 Seapp1@aol.com											Easting (X):	974,944
											Northing (Y):	898,466
											Horizontal System:	NAD 1983
											Vertical System:	NAVD 29


SIEVE ANALYSIS: SINGER_IS.GPJ FL DEP ROSS.GDT 9/7/04



Gravel		Sand			Silt and Clay
Coarse	Fine	Coarse	Medium	Fine	

Sample	Symbol	Elev.	Comments	USCS	% Fines	Median	Mean	Skew	Kurt	Sort	Sample Information	
SI04-17 #8.0	—●—	-60.5		SP	#200 - 0.90 #230 - 0.87	1.5	1.46	-0.21	2.6	0.92	Project Name:	Palm Beach County Vibracore 2004
											Analysis Date:	07-01-04
											Analyzed By:	SEA Inc.
Scientific Environmental Applications, Inc. 5575 Willoughby Drive Melbourne, FL 32934 (321) 254-2708 Seapp1@aol.com											Easting (X):	974,944
											Northing (Y):	898,466
											Horizontal System:	NAD 1983
											Vertical System:	NAVD 29

SIEVE ANALYSIS: SINGER_IS.GPJ FL DEP ROSS.GDT 9/7/04



SIEVE ANALYSIS: SINGER_IS.GPJ FL DEP ROSS.GDT 9/7/04

